CW1000-X Lyghtspeed Management Platform v1.0.4d(Rel 1. GA)
Error messages list

Table A1 - Main error codes for CW1000-X management platform

Error code	Description
45001	System has not finished initializing Try again in a few minutes
45002	A hardware module failure has occurred Contact TAC for assistance
45003	The main cryptographic module has failed to initialize
45004	Mgmtd daemon is not responsive
45005	Faild daemon is not responsive
45006	Replicated daemon is not responsive
45007	License invalid or expired
45008	Admin account locked out
45009	System credentials have not been set Default admin user password is set (see chassis serial number)
45010	Factory reset in progress
45011	System reboot in progress
45012	Power supply failure
45013	LI module cannot communicate with TETRA/OMEGA server
45014	LI module still initializing
45099	Unknown error has occured Contact TAC for assistance

Note 1. A valid maintenance contract is required for software/hardware support